Citations Home Page C0070013 # 3						
Citation for Non-Compliance Utah Coal Regulatory Program 1594 West North Temple, Salt Lake City, UT 84114 Phone: (801) 538-5340 Fax: (801) 359-3940		Citation #: 10086 Permit Number: C0070013				
		Date Issued: 06/08/2011				
NOTICE OF VIOLATION CESSATION ORDER (CO)			FAILURE TO ABATE CO			
Permittee Name: UTAHAMERICAN ENERGY INC In		ctor Number and ID: 46 PHESS				
Mine Name: HORSE CANYON MINE		Date and Time of Inspection: 06/07/2011 10:30 am				
Certified Return Receipt Number: 7008 0150 0002 0896 431 D			e and Time of Service: 06/08/2011 2299			
Nature of condition, practice, or violation: Conducting mine facilities construction (bulk rock dust tank installation) without properly permitting the new support facility and without receiving proper Division approval for same.						
Provisions of Act, regulations, or permit violated: R645-300-143; Compliance with Terms and Conditions of the Approved State Permit R645-301-111.200 Permittee Responsibility R645-301-830.140 Detailed Cost Estimate Sheet for New Facility						
This order requires Cessation of ALL mining activities. (Check box if appropriate.)						
	Permittee is/has been conducting mining activities without a Permit.					
reasonably be expected to cause significant, imminent	Permittee has failed to abate Violation(s) included in Notice of Violation or Cessation Order within time for abatement originally fixed or subsequently extended.					
This order requires Cessation of PORTION(S) of mining activities.						
Mining activities to be ceased immediately: ☐ Yes ✓	No		Abatemen	t Times (if app	plicable).	
Complete the required permitting activities listed below by:			by June 22,	, 2011 @ 17:00	Hours	
Action(s) required: Yes No 1) The Permittee must update Section 520, Operation Plan Facilities List, and Section 526, Support Facilities of the mining and reclamation plan to include the 30 Ton bulk rock dust storage tank. 2) Develop a demolition cost for removal of the bulk tank and its support structure. Update the reclamation cost estimate in the MRP (Appendix 8-1) to include this additional demolition and removal cost. 3) Update Plate 5-2, Surface Area, Official Disturbed Boundary Map / Mine Facility List to include the new bulk rock dust tank facility. Depict the location of this installation on Plate 5-2.						

SEE REVERSE SIDE Of This Form For Instructions And Additional Information

R. Jay Marshall

Permittee Representative's Signature - Date

PETE HESS

(Print) DOGM Representative

DOGM Representative's Signature Date

U.S. Postal Service 163 CERTIFIED MAIL RECEIPT (Domestic Mail Only; No Insurance Coverage Provided) 4327 0896 Postage Certified Fee Return Receipt Fee (Endorsement Required) Restricted Delivery Fee (Endorsement Required) Total Postage & Fees 7008 See Reverse for Instructions

07.50